UWPR lab specific guidelines

All users must abide by the guidelines outlined in the guidelines for COVID-19 prevention

General:

- Social Distancing: stay 6ft apart at all times
- Masks are to be worn in all common areas of the building as outlined by EH&S
- No more than three people should be working in the UWPR portion of the lab at any given time
- Do not enter Bruce lab space (green shaded area on floorplan)
- Wash hands when entering and before leaving the lab
- Users and visitors sign in and out when entering/leaving the lab (sign-up sheet is located next to the speed Vac)
- Use appropriate PPE including gloves, eye protection and lab coats

Instrument usage:

- Only touch surfaces related to the instrument you are using
- Surfaces including keyboard, mouse, fittings, table and chair will be wiped prior to your start time
- Users are responsible to clean surfaces prior and after use
- Methanol and Kim wipes to clean surfaces are available throughout the lab
- Date and initial the log when using and decontaminating surfaces and instruments
- Key cards and lanyards are sanitized prior to your start time
- After you are finished leave the key card on the computer desk by the instrument you used
- Put all used/touched fittings in the beaker labeled "used fittings" for sanitation

Common areas:

- Users must decontaminate all common surfaces and instruments (blue shaded area on floorplan) before and after use
- Date and initial the log when using and decontaminating surfaces and instruments
- Common instruments include microscopes, pressure cells and/or laser puller, centrifuges, pipettes
- This also applies if you use the office space, max occupancy is one person in the office
- Methanol and Kim wipes to clean surfaces are available throughout the lab

