


## SOP for Irritants

University of Washington

Standard Operating Procedures for Chemicals or Processes		
#1 Process (if applicable)		
#2 Chemicals	2X LAEMMLI SAMPLE BUFFER IODOACETIC ACID TYROSINE PBS PHOSPHATE BUFFERED SALINE ULTRAMARK(R) 1621, MASS SPEC STANDARD	
#3 Personal Protective Equipment (PPE)	<ul style="list-style-type: none"> <li>Safety glasses or goggles shall be worn during operations</li> <li>COMPOUNDS might contact the eyes (e.g., through vapors or splashes of solution).</li> <li>Use disposable nitrile gloves when working with chemicals.</li> </ul> Lab coats, closed toed shoes, long pants and long sleeved clothing shall be worn	
#4 Environmental / Ventilation Controls		
#5 Special Handling Procedures & Storage Requirements	Avoid contact with skin and eyes and inhalation. Store in a cool dry place.	
#6 Spill and Accident Procedures	Contain and/or absorb spill with inert material (e.g. sand, vermiculite), then place in suitable container and dispose of as hazardous waste	
#7 Waste Disposal	dispose of as hazardous waste	
#8 Special Precautions for Animal Use (if applicable)		
Particularly hazardous substance involved?	<input type="checkbox"/> YES:	Blocks #9 to #11 are Mandatory
	<input checked="" type="checkbox"/> NO:	Blocks #9 to #11 are Optional.
#9 Approval Required		
#10 Decontamination		
#11 Designated Area		
<div style="display: flex; justify-content: space-between;"> <span>Name: Priska von Haller</span> <span>Title: PhD</span> </div>		
<div style="display: flex; justify-content: space-between;"> <div style="width: 40%;">           Signature:  </div> <div style="width: 40%; text-align: right;">           Date: 5/13/2025         </div> </div>		

Environmental Health and Safety, Box 354400  
Supervisor

\*to be filled in by PI or